

Safety information

Summary of the most important safety information. The complete instructions are available via the QR code on the rating plate.

DANGER

Cuts from the running saw band. Never reach into the cutting area while the band is running.

WARNING

Ejected workpiece parts. Always clamp the workpiece in the vice.

- Only trained persons may operate the machine.
- Never remove or bypass protective covers.
- Always clamp the workpiece in the vice.
- Wear safety glasses, hearing protection and close-fitting clothing.
- Switch off and secure the main switch before maintenance and band changes.
- Check the emergency stop button before starting work.

DEMO